
Capability list- EASA 145- FAR 145

1. AIRCRAFT HYDRAULIC EQUIPMENT**1.1. AIRBUS A340 -500/-600 SERIES****HYDRAULIC RESERVOIR**

ATA 29-11-01 P/N: 42F1412, 42F1512, 42F1607

All repairs

1.2. AIRBUS A330/A340 -200/-300 SERIES**HYDRAULIC RESERVOIR**

ATA 29-11-11 P/N: 42F1005, 42F1203, 42F1304

All repairs

Capability list- EASA 145- FAR 145

2. ENGINE LUBRICATION ACCESSORIES**2.1. OVERHAUL – TEST & REPAIRS*****CFM56-2**

Lubrication Unit	ATA 79-21-11	P/N: 301-572-03X-0	All repairs
------------------	--------------	--------------------	-------------

CFM56-3

Lubrication Unit	ATA 79-21-12	P/N: 335-261-00X-0	All repairs
------------------	--------------	--------------------	-------------

CFM56-5A

Lubrication Unit	ATA 79-21-14	P/N: 336-010-00X-0	All repairs
------------------	--------------	--------------------	-------------

CFM56-5C/-5B

Lubrication Unit	ATA 79-21-15	P/N: 337-075-10X-0	All repairs
------------------	--------------	--------------------	-------------

CFM56-7B

Lubrication Unit	ATA 79-21-16	P/N: 41F100X, 340-400-00X-0	All repairs
------------------	--------------	-----------------------------	-------------

Oil Scavenge Filter Assembly	ATA 79-21-42	P/N: 41F900X, 340-400-30X-0	All repairs
------------------------------	--------------	-----------------------------	-------------

Static Anti-Leak Valve	ATA 79-21-43	P/N: 41F3003, 340-400-201-0	All repairs
------------------------	--------------	-----------------------------	-------------

Debris Monitoring System	ATA 79-21-54	P/N: 41F1204, 41F1205, 41F1303, 41F1304	All repairs
--------------------------	--------------	---	-------------

* X stands for a numeral

Capability list- EASA 145- FAR 145

GE90

Lubrication Unit	ATA 79-21-13	P/N: 40F100X, 350-328-00X-0, 350-050-005-0	All repairs
	ATA 79-21-58	P/N: 40F60XX	All repairs
Static Anti-Leak Valve	ATA 79-21-37	P/N: 350-106-40X-0	All repairs
	ATA 79-21-44	P/N: 40F000X, 350-716-80X-0	All repairs

V2500

No. 4 Bearing Compartment Scavenge Valve Unit	ATA 79-23-52	P/N: 32F0003	All repairs
---	--------------	--------------	-------------

LEAP 1A

Lubrication Unit	ATA 79-21-05	P/N B1316-06163, 362-074-103-0	All repairs
------------------	--------------	--------------------------------	-------------

LEAP 1B

Lubrication Unit	ATA 79-21-06	P/N B1316-06162, 364-074-102-0	All repairs
------------------	--------------	--------------------------------	-------------

Capability list- EASA 145- FAR 145

TP400-D6

Lubrication Unit TM	ATA 79-22-10	P/N: TA B1316-02059	P/N EPI TP531009	All repairs
Lubrication Unit PGB	ATA 79-22-50	P/N TA B1316-03700	P/N EPI TP531505	All repairs
Shut Off Valve	ATA 79-22-42	P/N TA B1316-02474	P/N EPI TP534520	All repairs

*Release under EASA Form 1 under Part 145 regulation if it is demonstrated that the engine has been used only for commercial operations.
In case such components are used for military applications, they will not be under BCAA supervision.*